HISTORIC AMERICAN BUILDINGS SURVEY

INDEX TO PHOTOGRAPHS

Randle Ranger Residence (Building #1135) Silverbrook Road Randle Lewis County Washington HABS No. WA-187

Don Busch, Photographer February 1982 (WA-187-2 and WA-187-3) R.H. McClure, Jr., Photographer February 1982 (WA-187-1, WA-187-4, WA 187-5)	
WA-187-1	CONTEXTUAL VIEW TO WEST, RANDLE RANGER RESIDENCE AND ASSOCIATED GARAGE ON BENCH ABOVE PASTURE AND SILVERBROOK ROAD.
WA-187-2	SOUTH FRONT AND EAST SIDE OF RANDLE RANGER RESIDENCE SHOWING PORCH, DORMER, AND 1936 KITCHEN/DINETTE ADDITION, VIEW TO WEST.
WA-187-3	EAST SIDE OF RANDLE RANGER RESIDENCE SHOWING 1936 KITCHEN/DINETTE ADDITION, VIEW TO SOUTHWEST.
WA-187-4	NORTH BACK OF RANDLE RANGER RESIDENCE FROM SLOPE AT REAR OF STRUCTURE. VIEW IS TO SOUTH-SOUTHEAST AND SHOWS 1936 LAUNDRY ROOM ADDITION.
WA-187-5	NORTHEAST INTERIOR CORNER OF 1936 KITCHEN/DINETTE ADDITION SHOWING CABINETS. VIEW IS TO NORTHEAST.